

Hrvoje Turkulin, Klaus Richter, Jürgen Sell¹

Adhesion of water-borne acrylic and hybrid paint on wood treated with primers²

Prianjanje vodotopljivih akrilnih i hibridnih boja na predpremazima obrađeno drvo

Original scientific paper • Izvorni znanstveni rad

Received – prispjelo: 28. 10. 2000 • Accepted – prihvaćeno: 05. 12. 2000

*UDK 630 * 829.1*

SUMMARY • *Spruce substrates of radial and tangential texture have been successfully treated with isocyanate-based and resorcinol-based primers to improve the adhesion of water-borne paint in dry and wet condition. Microscopic evidence shows that the wet adhesion of the acrylic or hybrid base-coats was severely impaired by the water ingress into these porous and brittle layers. Direct application of the top-coat on wood, especially on that treated with primers, proved advantageous over base-coat / top-coat system in terms of wet adhesion.*

Key words: *spruce, durability, adhesion, primers, water-borne paints, hybrid paints, SEM microscopy*

SAŽETAK: • *Postojanost ugrađenog drva uvelike ovisi o cjelovitosti i dobrom prianjanju (adheziji) zaštitnih i dekorativnih premaza. Trajnost premaza je određena fizikalnim svojstvima filma, ali podjednako je važna i veza premaza s drvom. Moderni vodotopljivi premazi, a naročito debeloslojne neprozirne boje, često iskazuju slabo prianjanje na mokrom drvu tj. popuštanje međusobne veze u uvjetima visoke vlažnosti i povišenog sadržaja vode drva u uporabi.*

¹ Dr Hrvoje Turkulin je docent na Šumarskom fakultetu Sveučilišta u Zagrebu, a Dr Klaus Richter i Prof. Jürgen Sell su, redom, znanstveni savjetnik i predstojnik na Odsjeku za ispitivanje drva Saveznog instituta za istraživanja i ispitivanja materijala (EMPA), Dübendorf, Švicarska.

Dr Hrvoje Turkulin is an assistant professor at the Faculty of Forestry of the Zagreb University; Dr Klaus Richter and Prof. Jürgen are a principal research scientist and a head, respectively, at the Wood Department of the Swiss federal laboratories for material testing and research (EMPA), Dübendorf, Switzerland.

² Rad je predstavljen na Drugom europskom kongresu o površinskoj obradi drva u Hagu u Nizozemskoj u listopadu 2000. Ovdje donosimo, s dozvolom organizatora, malo izmjenjeni oblik članka radi interesa šireg čitateljstva.

The paper has been presented at the Second wood coatings congress in The Hague, The Netherlands, in October 2000. We publish here, with the approval of the organizer, a slightly altered version of the text in order to present it to broader readership.

Table 1.

DRY TESTING RESULTS - Cumulative results of the adhesion testing (pull-off test according to EN 24 624) • REZULTATI SUHOG ISPITIVANJA – zbirni rezultati ispitivanja prijanjanja otkidanjem zalijepljenih kružića prema EN 24624)

TEST METHOD	FINISHING SYSTEM				PULL-OFF STRENGTH				FAILURE CHARACTERISTICS			COMMENTS PRIMJEDBE			
	SUSTAV POVRŠINSKE OBRADJE	BASE COAT	TOP COAT - ZAVRŠNI	PREMIER	ČVRSTOĆA PRIJANJANJA	INDEX TO CONTR.	FRACTURED SURFACE	ZNAČAJKE LOMA	WOOD	WOOD	FINISH		COMMENTS		
NACIN ISPITIVANJA	TEMELJNI SLOJ	WB	PB	ACRL.	HYBR.	PREMIER	ACRYLIC TOP COAT, 2X AKRILNI ZAVRŠNI NALIC 2X	PREMAZ	DRVO	LOMNA POVRŠINA	PREMAZ	PRIMJEDBE			
DRY ON RADIAL TEXTURE	WB	ACRL.	HYBR.	PREMIER	HYBR.	CONTROL	ACRYLIC TOP COAT, 2X AKRILNI ZAVRŠNI NALIC 2X	CONTROL	DRVO	LOMNA POVRŠINA	PREMAZ	PRIMJEDBE			
SUHO NA RADIAL TEXTURE	1X	-	-	1X	-	1X	ACRYLIC TOP COAT, 2X AKRILNI ZAVRŠNI NALIC 2X	CONTROL (no primer)	20 %	80% adhesion WB/wood		Good substrate and adhesion			
	-	1X	-	-	-	-	ACRYLIC TOP COAT, 2X AKRILNI ZAVRŠNI NALIC 2X	HMR	30 %	90% cohesion PB 70% adhesion WB		→ on earlywood zones → on latewood zones			
	-	-	-	-	-	-	ACRYLIC TOP COAT, 2X AKRILNI ZAVRŠNI NALIC 2X	HMR		60% interface failure 40% cohesion WB 50% cohesion PB		(Finish not tested)			
SUHO NA TANG.	1X	-	-	1X	-	1X	ACRYLIC TOP COAT, 2X AKRILNI ZAVRŠNI NALIC 2X	IC	80%	90 % Cohesion WB		Some interface failure			
	-	1X	-	-	-	-	ACRYLIC TOP COAT, 2X AKRILNI ZAVRŠNI NALIC 2X	IC	80%	20% Cohesion PB					
	-	-	-	-	-	-	ACRYLIC TOP COAT, 2X AKRILNI ZAVRŠNI NALIC 2X	IC	80%	20% Cohesion WT					
SUBSTRATE PODLOGA	-	-	-	-	-	-	ACRYLIC TOP COAT, 2X AKRILNI ZAVRŠNI NALIC 2X			10% coh. WT 40% coh. WB 10% coh. WB 90% adhesion WB		HMR primer improves adhesion and strength of basecoat			
	-	1X	-	-	-	-	ACRYLIC TOP COAT, 2X AKRILNI ZAVRŠNI NALIC 2X			90% adh. WT/wood 60% adh. WB/wood					
	-	-	-	-	-	-	ACRYLIC TOP COAT, 2X AKRILNI ZAVRŠNI NALIC 2X			90% adh. WT/HMR					
									8	5,70	0,86	1,27	100%		

Table 2.

WET TESTING RESULTS - Cumulative results of the adhesion testing (pull-off test according to EN 24 624) • REZULTATI MOKROG ISPITIVANJA – zbirni rezultati ispitivanja prijanjanja otkidanjem zalijepljenih kružića prema EN 24624)

TEST METHOD	FINISHING SYSTEM				PULL-OFF STRENGTH				FAILURE CHARACTERISTICS		COMMENTS PRIMJEDBE
	SUSTAV POVRŠINSKE OBRADJE		ČVRSTOĆA PRIJANJANJA		ZNAČAJKE LOMA		FRACTURED SURFACE		WOOD DRYO	LOMNA POVRŠINA	
NACIN ISPITIVANJA	PRIMER PREDPREMAZ	BASE COAT		X N/mm ²	S N/mm ²	INDEX TO CONTR.	N ^o OF TESTS BROJ MJERENJA	WOOD DRYO			FINISH PREMAZ
		WB ACRL.	PB HYBR.						INDEX TO CONTR.	FINISH PREMAZ	
WET ON RADIAL TEXTURE	CONTROL (no primer)	1X	-	1,20	0,74	1,00	10			50% adh. WB/wood	50% coh. WB
	HMR	-	1X	1,78	0,67	1,48	11			100% cohesion PB	100% cohesion PB
	HMR	-	-	2,26	0,57	1,88	8			100% adhesion WT	100% adhesion WT
WET ON RADIAL TEXTURE	HMR	1X	-	1,77	0,46	1,48	10	20 %		70% coh. WB	10% WT/epoxy adh.
	HMR	-	1X	2,05	0,97	1,71	12	50 %		80% adh. WT/PB	20% coh. PB
	HMR	-	-	2,80	1,02	2,33	12			(50% HMR interface)	50% epoxy adh.
WET-TANGENT.	IC	1X	-	2,00	0,42	1,67	10			60% coh. WB	40% adh. WT/epoxy
	IC	-	1X	3,17	0,86	2,64	12	30 %		60% cohesion PB	10% WT to epoxy adhesion
	IC	-	-	3,03	0,69	2,53	12	10 %		50% adhesion WT to IC	40% WT to epoxy adhesion
WET-TANGENT.	-	-	-	1,25	0,68	1,04	6			100% adhesion WT on wood	Moist. content: end grain 40 - 75%
	-	1X	-	0,96	0,32	0,80	6			60% coh. WB	40% adh. WB/wood
	HMR	-	-	1,44	0,38	1,20	6			50% adh. WB/HMR	50% adh. epoxy
	HMR	1X	-	1,70	0,28	1,42	6			60% coh. WB	40% adh. epoxy

water infiltration leads to the swelling and the separation within the layer. It is suspected that the advantage of great micro-porosity of a basecoat during storage and transport of unfinished products becomes a major disadvan-

tage i.e. the weakest point of the system. Liquid water can penetrate through cracks or migrate from deeper wood areas to its surface, nest in the voids of the porous base-coat and further reduce its coherence.

Figure 2.

Photograph of the surfaces tested dry for adhesion in pull-off test. Paler areas show wood failure, white areas show top-coat remnants, dark grey areas present base-coat deposit. ●
 Fotografija ispitnih površina suhog prijanjanja nakon testa otkidanjem kružića. Svijetle površine pokazuju lom po drvu, bijele su ostaci završnog naliča, a tamno sive su plohe slojevi temeljne boje.



Figure 3.

Photograph of the surfaces tested dry for adhesion in pull-off test. Predominantly greyish surfaces depict failure at the border between the base-coat and primed wood surface. ●
 Fotografija ispitnih površina suhog prijanjanja nakon testa otkidanjem kružića. Prevladavajuće sive površine su posljedica loma na granici između slojeva temeljne boje i predpremazanoga drva.




Figure 4.

Photograph of the surfaces tested wet for adhesion in pull-off test. Predominant base-coat failure on primed wood. ●
 Fotografija ispitnih površina mokrog prijanjanja nakon testa otkidanjem kružića. Prevladava lom u sloju temeljne boje nanešene na predpremazom obrađeno drvo.



Figure 6.

Control specimen:
fractured end-grain –
surface of the genuine,
painted spruce wood.
Base-coat shows
brush-like appearance.
Earlywood tracheids fail
in the same mode as
unmodified wood. 1100:1
• Kontrolni primjerak:
poprečna lomna površina
smrekovine bojane bez
predobrade. Sloj temeljne
boje odaje krhka svojstva.
Traheide ranog drva
pucaju na isti način kao i
neobrađeno drvo. 1100:1.




Figure 7.

Control specimen:
fractured end-grain –
surface of the genuine,
painted spruce wood. Two
adjoining cell walls show
tough failure
characteristics as in
unmodified wood.
Base-coat (upper) adheres
good to the S3 layer of the
upper cell wall. 10000:1
• Kontrolni primjerak:
poprečna lomna površina
smrekovine bojane bez
predobrade. Dvije
susjedne stanične stijenke
pokazuju žilava lomna
svojstva kao kod
neobrađenog drva. 10000:1.





Figure 8.

Control specimen:
fractured end-grain –
surface of the genuine,
painted spruce wood.
Resin deposit within the
lumen of the lower cell
wall. Complete
detachment of the paint
in the upper lumen due to
poor adhesion and/or
testing stress. 4500:1
• Kontrolni primjerak:
poprečna lomna površina
smrekovine bojane bez
predobrade. Naslage boje
unutar lumena na donjoj
staničnoj stijenki. Potpuno
odvajanje boje u gornjem
lumenu pokazuje ili slabo
prianjanje ili(i) posljedice
naprezanja pri lomu.






Figure 9.
HMR specimen: fractured end-grain – surface of the HMR primer impregnated and painted spruce wood. Earlywood failure mode closely resembles failure mode on control specimens. 400:1 • HMR uzorak: poprečne površine smrekovine obrađene rezorcinskim predpremazom i bojom. Vrsta loma ranog drva blisko slični na lomne površine kontrolnih uzoraka. 400:1.




Figure 10.
HMR specimen: fractured end-grain – surface of the the HMR primer impregnated and painted spruce wood. Resin deposit within the lumen and fairly good attachment to the cell walls is obvious. 1100:1 • HMR uzorak: poprečne površine smrekovine obrađene rezorcinskim predpremazom i bojom. Vidljiva je naslaga smole u unutrašnjosti lumena i prilično dobro prihvaćanje uz staničnu stijenku. 1100:1.




Figure 11.
HMR specimen: fractured end-grain – surface of the the HMR primer impregnated and painted spruce wood. It is supposed that the upper lumen is filled with thick-layer forming base-coat, while the deposit in the lower lumen is primer's resorcinol resin. These two materials and the border between them can not be distinguished on SEM images. Structural appearance of the cell wall structure indicates that no penetration of the primer into the wall body, especially into S2 layer, has occurred. 1000:1 • HMR uzorak: poprečne površine smrekovine obrađene rezorcinskim predpremazom i bojom. Pretpostavlja se da je gronji lumen ispunjen debeloslojnom temeljnom bojom, dok je naslaga u donjem lumenu rezorcinska smola predpremaza. Ova dva sloja tj. granica među njima se ne mogu raspoznati na SEM slikama. Strukturni izgled stanične stijenke naznačuje da nije došlo do prodiranja predpremaza u staničnu stijenku, pogotovo ne u S2 podsloj.

Figure 12.

IC specimen: fractured end-grain – surface of the the isocyanate primer-impregnated and painted spruce wood. Earlywood failure mode closely resembles failure mode on control and on HMR primer-impregnated specimens. 400:1 • IC uzorak: poprečne površine smrekovine obrađene izocijanatnim predpremazom i bojom. Način loma ranog drva blisko slični onom na kontrolnim i na HMR uzorcima. 400:1.




Figure 13.

Optical (reflected fluorescence light) micrograph of the end-grain surface of spruce wood impregnated with HMR primer and painted with water-based system. Deep penetration of the primer (dark areas) is obvious. Layers of the base-coat and two top coats could not be differentiated. • Optička mikrografija (odbijenim fluorescentnim svjetlom) površine poprečnog presjeka smrekovine obrađene HMR resorcinским predpremazom i vodotopljivim sustavom boje. Jasno se vide tamne zone duboke penetracije predpremaza. Nije moguće razlikovati temeljni od dva sloja završne boje.





Figure 14.

Optical (reflected ultra-violet light) micrograph of the end-grain surface of spruce wood impregnated with isocyanate primer and painted with water-based system. Shallow penetration of the primer (glooming areas) can be seen. Layers of the base-coat and two top coats could not be differentiated. • Optička mikrografija (odbijenim ultra-ljubičastim svjetlom) površine poprečnog presjeka smrekovine obrađene izocijanatnim predpremazom i vodotopljivim sustavom boje. Može se vidjeti plitka penetracija predpremaza (sjajnija područja). Nije moguće razlikovati temeljni od dva sloja završne boje.



- In: Advances in exterior wood coatings and CEN standardisation (Conference proceedings, paper 18). PRA conference Brussels, 1998. Paint Research Association, Teddington UK.
8. Vick, C.B.; Richter, K.H.; River, B.H. (1996): Hydroxymethylated resorcinol coupling agent and method for bonding wood. Inventors, USDA, assignee. Patent 5.543.487.
9. Vick, C.B. (1997): Enhanced adhesion of melamine-urea and melamine adhesives to CCA-treated southern pine lumber. Forest Prod. J. 47 (7/8): 83-87.
-

Obavjest

U sljedećem broju časopisa objavljujemo članak:

"HRVATSKI DRVARSKI ŽIVOTOPISNI LEKSIKON"

Prikupljanje i ažuriranje podataka za sve profesore, nastavnike, doktore, magistre, diplomirane inženjere i inženjere drvne industrije i drvne tehnologije! Pročitajte članak i javite se uredništvu leksikona svojim prilogom.